



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 298/2023

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 664
 BA 3446

**TOK BALI FAIRWAY LIGHT BUOY RESTORED TO NORMAL
KELANTAN WATERS**

Mariners are advised that Tok Bali fairway light buoy has been restored to normal. The details are as follows:

Name : **Tok Bali Fairway**

Position : **Lat. 05° 56.000' N**
Long. 102° 30.400' E
(Datum: WGS-84)

Light Characteristic : LFI.W.10s

Mariners are advised to navigate with caution when in the vicinity.
This notice cancels **NTM 286(T)/2023**.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
25th December 2023