



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
P.O BOX 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS NTM 70/2024

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kemaman Port
Charts Affected : MAL 6416
 BA 1374

**KEMAMAN BREAKWATER SOUTH LIGHT BEACON RESTORED TO NORMAL
TERENGGANU WATERS**

Mariners are advised that Kemaman Breakwater South light beacon has been restored to normal.

Name : Kemaman Breakwater South
Position : Lat. 04° 13.768' N
 Long. 103° 27.127' E
Light Characteristic : FL.Y.3s

Mariners are advised to navigate with caution in the area.
This notice cancels NTM 34(T)/2024.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
3rd April 2024.
