



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUATERS, MENARA DIUS API
P.O BOX 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 71(T)/2024

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : South China Sea, Kuantan Port
Charts Affected : MAL 6359
BA 3446 & BA 1379

KUANTAN PORT LEADING LIGHT 311° 04' REAR LIGHT BEACON UNLIT SOUTH CHINA SEA

Mariners are advised that Kuantan Port Leading Light 311° 04' rear light beacon is unlit.

Name : Kuantan Port Leading Light 311° 04' Rear
Position : Lat. 03° 58.940' N
Long. 103° 25.490' E
Light Characteristic : Oc.G.5s

Mariners are advised to navigate with caution in the area.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
3rd April 2024.