



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUARTERS, MENARA DIUS API**  
**PO BOX 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



**PENINSULAR NOTICE TO MARINERS      NTM 73(T)/2024**

Telefon           : 03-3346 7777   Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
 Faksimili       : 03-3168 5289   Laman Web     : <http://www.marine.gov.my>

Authority           : Director of Marine, Malaysia

Position           : Johor waters

Charts Affected   : MAL 65, MAL 515  
                           BA 3831

**POST INSTALLATION SURVEY OF ASIA DIRECT CABLE (ADC) SYSTEM  
 JOHOR WATERS**

Mariners are advised that post installation survey of Asia Direct Cable (ADC) system will be carried out by Ben Line Agencies Malaysia Sdn Bhd.

Duration: **10th April – 30th April 2024**

Vessels Involve:

| Name         | Type          | Flag      | Call Sign |
|--------------|---------------|-----------|-----------|
| EGS Surveyor | Survey vessel | Indonesia | PORX      |

Area: The work area is enclosed by an imaginary lines connecting the following points :

| Point | Latitude      | Longitude       |
|-------|---------------|-----------------|
| 175a  | 1° 17.6646' N | 104° 21.4417' E |
| 176   | 1° 17.6829' N | 104° 21.4619' E |
| 177   | 1° 17.8621' N | 104° 21.579' E  |
| 178   | 1° 17.9042' N | 104° 21.5894' E |
| 179   | 1° 18.3077' N | 104° 21.6888' E |
| 180   | 1° 18.5019' N | 104° 21.7672' E |
| 181   | 1° 18.637' N  | 104° 21.879' E  |

|      |               |                 |
|------|---------------|-----------------|
| 182  | 1° 19.049' N  | 104° 22.4032' E |
| 183  | 1°19.2007' N  | 104° 22.5233' E |
| 184  | 1° 19.4167' N | 104° 22.6224' E |
| 185  | 1° 19.5381' N | 104° 22.6781' E |
| 186  | 1° 19.8719' N | 104° 22.99' E   |
| 187  | 1° 19.9021' N | 104° 23.0218' E |
| 188  | 1° 20.387' N  | 104° 23.5958' E |
| 189  | 1° 20.6547' N | 104° 24.0033' E |
| 190  | 1° 21.1364' N | 104° 24.5061' E |
| 191  | 1° 21.2848' N | 104° 24.7265' E |
| 192  | 1° 21.561' N  | 104° 25.1363' E |
| 193  | 1° 21.6767' N | 104° 25.2616' E |
| 194  | 1° 21.6899' N | 104° 25.3013' E |
| 195  | 1° 21.6995' N | 104° 25.3301' E |
| 196  | 1° 21.6939' N | 104° 25.5737' E |
| 197  | 1° 21.6909' N | 104° 25.7013' E |
| 198  | 1° 21.7338' N | 104° 25.8184' E |
| 199  | 1° 21.8259' N | 104° 25.9292' E |
| 200  | 1° 22.095' N  | 104° 26.2531' E |
| 201  | 1° 22.2426' N | 104° 26.4459' E |
| 202  | 1° 22.321' N  | 104° 26.5482' E |
| 203  | 1° 22.37' N   | 104° 26.6204' E |
| 204  | 1° 22.4048' N | 104° 26.6807' E |
| 205  | 1° 22.4152' N | 104° 26.7249' E |
| 206  | 1° 22.4344' N | 104° 26.8065' E |
| 207  | 1° 22.3231' N | 104° 27.1067' E |
| 208  | 1° 22.3391' N | 104° 27.1718' E |
| 208a | 1° 22.436' N  | 104° 27.3031' E |

*Above coordinates are referenced to Datum: WGS-84*

Mariners are advised to navigate with caution when in the vicinity and keep clear of the working area.

**( NURUL SUHANA BINTI SULAIMAN )**

for The Director General,  
Malaysia Marine Department.  
10<sup>th</sup> April 2024