



**MALAYSIA MARINE DEPARTMENT**  
**MARINE HEADQUARTERS, MENARA DIUS API**  
**PO BOX 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



**PENINSULAR NOTICE TO MARINERS      NTM 81(T)/ 2024**

Telefon           : 03-3346 7777    Emel               : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili       : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

---

Authority               : Director of Marine, Malaysia

Position                : Port Klang Waters

Charts Affected       : MAL 5307  
                              BA 3945

---

**TAIL LIGHT BUOY UNLIT**  
**PORT KLANG**

---

Mariners are advised that Tail light buoy is unlit. The details are as follow:

Name                    : **Tail**

Position                : **Lat    03° 00.390' N**  
                              **Long 101° 21.215' E**

Light Characteristic : **Q.W** ( North Cardinal Mark )

Mariners are advised to navigate with caution when in the vicinity.

**( EMIZUL FADLY MASDEK )**  
for The Director General,  
Malaysia Marine Department.  
24<sup>th</sup> April 2024.