



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



PENINSULAR NOTICE TO MARINERS NTM 92 (T)/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Kuantan Port, Pahang

Charts Affected : MAL 6359
BA 1379

SOUTH BREAKWATER HEAD LIGHT BEACON UNLIT KUANTAN PORT, PAHANG

Mariners are advised that Kuantan South Breakwater Head Beacon are temporarily unlit. The details are as follows:

Name : Kuantan South Breakwater Head Beacon

Position : Lat. 03° 58.080 N
Long. 103° 26.610 E

Light Characteristic : Fl.(4) R.12s

Mariners are advised to navigate with caution when in the vicinity.

(Ts. MUHAMMAD FADHLI BIN MAKHTAR)

for The Director General,
Marine Department Malaysia.
21th May 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602