



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
PT 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 187(T)/2024

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Johor Waters, Tg.Penyusup

Charts Affected : MAL 6124
BA 4042 & BA 3831

**KD PENDEKAR WRECK LIGHT BUOY ALTERED IN POSITION
JOHOR WATERS**

Mariners are advised that a temporary light buoy has been altered in position. The details are as follows:

Name : **KD PENDEKAR WRECK**

Position : Lat. **01° 20.880'N**
Long. **104° 18.500' E**
(Datum: WGS-84)

Light
Characteristic: **FL.2 W 10s**

Type : **Isolated Danger Mark**

Marines are advised to navigate with extra caution in the vicinity.
This notice cancels NTM 167(T)/2024.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
25th September 2024