



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS, MENARA DIUS API
PT 664, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 205(T)/2024

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Malacca Strait

Charts Affected : MAL 54 & MAL 540
BA 3901 & BA 3945

ONE FATHOM BANK LIGHTHOUSE UNRELIABLE MALACCA STRAIT

Mariners are advised that the One Fathom Bank lighthouse is unreliable due to essential maintenance works with a revised nominal range of 16Nm. The details are as follows:

Name : ONE FATHOM BANK
Position : Lat 02° 53.31' N
Long. 100° 59.72' E (*Datum: WGS-84*)
Light Character : FL(4) W 20S
Range : 16 Nm

Marines are advised to navigate with extra caution.

(EMIZUL FADLY MASDEK)
for The Director General,
Malaysia Marine Department.
15th October 2024