



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 168 (T)/2019

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Strait
Charts Affected : MAL 532, MAL 540 & MAL 54
 BA 2139, BA 3940 & BA 3946

ONE FATHOM BANK LIGHTHOUSE REDUCED POWER MALACCA STRAIT

Mariners are advised that One Fathom Bank Lighthouse is temporarily operating on reduced power and light nominal range is reduced to 15 nautical miles. The details are as follows:

Name : One Fathom Bank
Position : Lat. 02° 53.31' N
 Long. 100° 59.72' E
Elevation : 43 m from MHWS
Characteristic : FI (4) W 20S

Mariners are advised to navigate with extra caution when in the vicinity.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
9th October 2019