



**JABATAN LAUT SABAH**  
**MARINE DEPARTMENT SABAH**



MS ISO 9001:2000  
Approval Cert. No: 403591 W

**NOTICE TO MARINERS NO. 46 (T) OF 2009**

Marine Department HQ, No. 2, Sabah Marine Department Complex, Salut Bay, Sepanggar Road, 88450 Kota Kinabalu, Sabah.

Tel: 6 088 401111 Fax: 6 088 401182 E-mail: Azmanlatip@jlsbh.gov.my Web Site: <http://www.jlsbh.gov.my>

Authority : Director of Marine, Sabah  
Position : Sabah Water, Malaysia  
Charts Affected : BA 1338, BA 2576, BA 3483, MAL 871

**BUOY AND BEACON REPORTED MISSING**


Mariners are informed that the following buoy and beacon reported missing :

Name : **Gibson Reef**  
Position : Lat 06° 50' 41" N Long 117° 32' 15" E  
Light Characteristic : F 1 G 3s 7m 5M  
Structure : Buoy

Name : **Terusan Duyong**  
Position : Lat 05° 48' 28" N Long 118° 08' 56" E  
Light Characteristic : F 1 R 5s 5M  
Structure : Beacon

Name : **SE Pulau Selingan**  
Position : Lat 06° 50' 41" N Long 117° 32' 15" E  
Light Characteristic : F 1 G 3s 7m 5M  
Structure : Beacon

Mariners are advised to navigate with extra caution when approaching the vicinity.

  
**(AZMAN BIN AB LATIP)**  
For Director of Marine, Sabah  
Marine Department Sabah.  
31<sup>st</sup> December 2009