



**HYDROGRAPHIC OFFICE  
SARAWAK MARINE DEPARTMENT**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL : 082-484159 TELEX : LAUT MA 70933 FAX : 082-331778, 082-339422  
Website : www.jls.gov.my



**BORNEO NORTH WEST COAST**

**\*33/2009 – KUALA BARAM - RE-LOCATION OF CHANNEL BUOYS**

The Kuala Baram Channel Buoys No. 1 and No. 2, have been re-located at new positions as follows :

Buoy No.	New Position		Light Characteristics
	Latitude	Longitude	
1	04° 37' 50".998 N	113° 56' 19".004 E	<i>Fl.G.4s</i>
2	04° 35' 45".002 N	113° 58' 03".004 E	<i>Fl.R.4s</i>

2. **Delete** – Buoy No. 3 and No. 4

3. Mariners are advised to use the New Edition SAR 421-Kuala Baram nautical chart (28<sup>th</sup> April 2009) for the latest and up-to-date hydrographic data.

Chart : SAR 421

Source : Sarawak Marine Department

Date : 29<sup>th</sup> April 2009

**"BERKHIDMAT UNTUK NEGARA"**

[SARKAWI BIN NUMAN]

For Director of Marine Sarawak