



**HYDROGRAPHIC OFFICE  
SARAWAK MARINE DEPARTMENT**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL : 082-484159 TELEX : LAUT MA 70933 FAX : 082-331778, 082-339422  
Website : [www.jls.gov.my](http://www.jls.gov.my)



---

**BORNEO NORTH WEST COAST**

**41/2009(T) – BINTULU PORT, SOUTH ACCESS CHANNEL - BUOY F - UNLIT**

**Bintulu Port, South Access Channel, Buoy F, Fl.R.5s** at position **03 ° 15' 33".231 N, 113 ° 01' 09".926 E** has been reported unlit.

2. Mariners are advised to take extra caution when navigating in the area.

Chart : SAR 4001  
Source : Sarawak Marine Department  
Date : 15<sup>th</sup> June 2009

**"BERKHIDMAT UNTUK NEGARA"**

**[AHMAD FAIZAL BIN AHMAD FUAD]**  
For Director of Marine Sarawak