



**HYDROGRAPHIC OFFICE  
SARAWAK MARINE DEPARTMENT**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL : 082-484159 TELEX : LAUT MA 70933 FAX : 082-331778, 082-339422  
Website : [www.jls.gov.my](http://www.jls.gov.my)



---

**BORNEO NORTH WEST COAST**

**5/2009(T) – KUALA KEMENA , FAIRWAY BUOY - MISSING**

Kuala Kemena , Bintulu Fairway Buoy, *Fl.R.4s* at position 03° 11' 32".210 N, 113° 00' 25".180 E has been reported missing.

2. Mariners are advised to take extreme caution when navigating in the area.

Chart : SAR 402  
Source : Sarawak Marine Department  
Date : 19<sup>th</sup> January 2009

**"BERKHIDMAT UNTUK NEGARA"**

**[SARKAWI BIN NUMAN]**  
For Director of Marine Sarawak