



HYDROGRAPHIC OFFICE  
SARAWAK MARINE DEPARTMENT

NOTICE TO MARINERS  
(NOTIS PELAUT)

TEL : 082-484159 TELEX : LAUT MA 70933 FAX : 082-331778, 082-339422  
Website : www.jls.gov.my



BORNEO NORTH WEST COAST

24/2010(T) - TANJUNG MANIS – STARBOARD-HAND BUOY (No. 7) –  
OUT OF POSITION

Mariners are informed that the Starboard-hand Buoy (No. 7), Tanjung Manis, Batang Rajang is **out of position**. (Current position: 02° 07' 32".3 N, 111° 20' 22".8 E)

Charted (actual) position: *02 °07' 54".1 N, 111 °20' 33".0 E*

Charts : SAR 1440 & SAR 15  
Publication : Sarawak Nautical Almanac – SNP-4  
Source : Sarawak Marine Department  
Date : 23<sup>rd</sup> April 2010

"BERKHIDMAT UNTUK NEGARA"

[SARKAWI BIN NUMAN]  
For Director of Marine Sarawak