



**HYDROGRAPHIC OFFICE
SARAWAK MARINE DEPARTMENT**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL : 082-484159 TELEX : LAUT MA 70933 FAX : 082-331778, 082-339422
Website : www.jls.gov.my



BORNEO NORTH WEST COAST

***59/2010 – KUALA KEMENA, BINTULU -NAVIGATIONAL BUOYS - RE-ESTABLISHED**

Insert:

- i. Port-hand Buoy, *FL.R.4s* at position *03°11'05".25 N, 113°01'16".01 E*, Kuala Kemena, Bintulu, Sarawak.
 - ii. Starboard-hand Buoy, *FL.G.4s* at position *03°11'06".31 N, 113°01'39".56 E*, Kuala Kemena, Bintulu, Sarawak.
2. Mariners are advised to update their affected charts accordingly.

Charts : SAR 402, SAR 401
Source : Sarawak Marine Department
Date : 19th November 2010

"BERKHIDMAT UNTUK NEGARA"

[SARKAWI BIN NUMAN]
For Director of Marine Sarawak