



**JABATAN LAUT SEMENANJUNG MALAYSIA
MARINE DEPARTMENT PENINSULAR MALAYSIA**

NOTICE TO MARINERS

NTM 102(T)/1999

Marine Department HQ, Peninsular Malaysia, P.O. Box 12, 42007 Port Klang, Malaysia.

Tel: 03 3686616

Fax: 03 368 5289

E-mail: kpgr@marine.gov.my

Web site: <http://www.marine.gov.my>

Authority : Director General of Marine, Peninsular Malaysia

Position : MALACCA STRAITS

Charts Affected : BA 3946 , MAL 532

Publication Affected: NP 44, NP 79

**NEW LIGHT BUOY ESTABLISHED - MALACCA STRAITS TRAFFIC
SEPARATION SCHEME (TSS)**

1. **Mariners are advised that an Isolated Danger light buoy has been established for marking the wreck of MV JENWIN. Details of the buoy are as follow :-**

Position: Latitude 02° 16.07 ' N

(approx) Longitude 101° 47.69' E

Light Characteristic: FL(2)W 10s

Range: 7 N.M.

Colour: Black with a red horizontal band

Shape: Pillar

Top Mark: Double Black Sphere

2. **Mariners are advised to navigate with extreme caution when navigating in the vicinity.**

(Capt. Nazri Bin Abu Hassan)

for Director General of Marine
Peninsular Malaysia.

20 December 1999