



**JABATAN LAUT SEMENANJUNG MALAYSIA
MARINE DEPARTMENT PENINSULAR MALAYSIA**

NOTICE TO MARINERS

NTM 76/1999

Marine Department HQ, Peninsular Malaysia, P.O. Box 12, 42007 Port Klang, Malaysia.
Tel: 03 3686616 Fax: 03 3685289 E-mail: kpgr@marine.gov.my Web site: <http://www.marine.gov.my>

Authority : Director of Marine, Peninsular Malaysia

Position : Malacca Straits

Charts Affected : BA 3945 and 3946

Publication Affected: NP 79

ONE FATHOM BANK BEACON - CHANGE OF LIGHT CHARACTERISTICS

1. **Mariners are advised that with immediate effect the above light beacon characteristics have been changed as follows :-**

Name : ONE FATHOM BANK BEACON

Position : LAT. 03° 00.9 N LONG. 100° 51.9 E

**Light Characteristics : FI W 3 sec
(New)**

Notes : RACON (T) has been installed.

All other particulars of the beacon remain unchanged.

(Capt. Nazri Bin Abu Hassan)

for Director of Marine
Peninsular Malaysia.

15 September 1999