



**JABATAN LAUT SEMENANJUNG MALAYSIA
MARINE DEPARTMENT PENINSULAR MALAYSIA**

NOTICE TO MARINERS

NTM 01/2000

Marine Department HQ, Peninsular Malaysia, P.O. Box 12, 42007 Port Klang, Malaysia.

Tel: 03 3695100

Fax: 03 3685289

E-mail: kpgr@marine.gov.my

Web site: <http://www.marine.gov.my>

Authority : Director of Marine, Peninsular Malaysia

LIST OF NOTICE TO MARINERS STILL IN FORCE

1. **The following permanent Notice To Mariners were promulgated in 1999 are still in force**

<u>No</u>	<u>Title</u>
03/1999	Corrigendum to NTM 75/1998 - Wreck in position 01°58.56 N 102°21.14 E
05/1999	New light house established- One Fathom Bank, Malacca Strait
06/1999	New light beacon established - Malacca Strait
07/1999	New light beacon established- Malacca Strait
08/1999	New lightbeacon established -Malacca Strait
10/1999	New lightbeacon established -Kuala Dungun
11/1999	New pipelines and C.B.M established -Port Dickson
19/1999	Corrigendum to NTM 11/1999
31/1999	Corrigendum to NTM 74/1998
40/1999	New lightbeacon established Rumenia Shoal-South China Sea
43/1999	Tanjung Piai light buoy back on station
47/1999	Pipelines established - Off shore Trengganu
54/1999	Masa oilfield-South China Sea
60/1999	Light buoys back on station
62/1999	New light beacon established Pulau Jarak- Malacca Strait
71/1999	Bukit Segenting light intensity restored - Malacca Strait
72/1999	Pulau Mungging Racon (N) restored
76 1999	One Fathom Bank beacon -change of light characteristics
83/1999	Racon set installed on oil platforms
84/1999	Tanjung Pelepas port -light buoys established
85/1999	Racon (C) established -Sepat lightbeacon
96/1999	New lightbeacon established-Malacca Strait
97/1999	Lightbeacon (new) NW1 -Malacca Strait
104/1999	Wreck S.S Sun Vista
106/1999	Light beacon re-established -Malacca strait

2. **The following Temporary Notice To Mariners were promulgated in 1999 are still in force. All other temporary notices for 1999 are to be considered as having expired or superseded.**

<u>No</u>	<u>Title</u>
12(T) /1999	Lightbeacon destroyed
65(T) /1999	New wreck in the Straits of Malacca
100 (T)/1999	Seismic survey activities in Malacca Strait

No**Title**

101 (T)/1999	New wreck in Malacca Strait Traffic Separation Scheme (TSS)
102 (T)/1999	New light buoy established-Malacca strait TSS
103 (T)/1999	Removal of navigational hazards associated with the wreck of "Maritime Fidelity"
105(T)/1999	Addendum to NTM 101(T)/1999
107(T)/1999	Submarine cable repair - Malacca Strait

(Capt. Nazri Bin Abu Hassan)

for Director of Marine
Peninsular Malaysia.
03 January 2000