



**JABATAN LAUT SEMENANJUNG MALAYSIA
MARINE DEPARTMENT PENINSULAR MALAYSIA**

NOTICE TO MARINERS

NTM 16/2001

Marine Department HQ, Peninsular Malaysia, P.O. Box 12, 42007 Port Klang, Malaysia.

Tel: 03 31695100 Fax: 03 3168 5289 E-mail: kpgr@marine.gov.my Web site: <http://www.marine.gov.my>

Authority : Director of Marine, Peninsular Malaysia

Position : East Coast , Malaysia

Charts Affected : BA 771 and 3543

ISOLATED DANGER LIGHT BUOY ESTABLISHED

Mariners are advised that an Isolated Danger light buoy has been established.
Details of the buoy are as follow :-

Position:	Latitude	05° 52.833 ' N
(wgs 84)	Longitude	102° 38.434' E
Light Characteristic:	FL(2)W 10s	
Colour:	Black with a red horizontal band	
Shape:	Pillar	
Top Mark:	Double Black Sphere	

(Capt. Nazri Bin Abu Hassan)
for Director General of Marine
Peninsular Malaysia.
14 May 2001