



**JABATAN LAUT WILAYAH TENGAH
(SELANGOR, NEGERI SEMBILAN & MELAKA)
PETI SURAT 268, JALAN FORESHORE
42000 PELABUHAN KLANG
SELANGOR, MALAYSIA**

Telefon: 03-3169 5100
Faks: 03-3165 3540

Emel : pjlwt@marine.gov.my
Laman Web : <http://www.marine.gov.my>
Kawat : MARINE PELABUHAN KLANG



MS ISO 9001
Cert. No : KLR 0403591 B
Cert. No : KLR 0403591 N
Cert. No : KLR 0403591 M

PEKELILING PELABUHAN NO. 12/2010
PORT CIRCULAR NO. 12/2010

DARIPADA : PENGARAH LAUT WILAYAH TENGAH
FROM : DIRECTOR OF MARINE CENTRAL REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN
PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA
TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS &
AGENTS AND THE GENERAL SHIPPING COMMUNITY

TARIKH / DATED : 14hb Julai 2010 / 14th July 2010

**KERJA-KERJA Pengerukan Dihadapan
DERMAGA NORTHPORT (DERMAGA 8
HINGGA 25) DAN DIHADAPAN DERMAGA
SOUTHPOINT (DERMAGA 1 HINGGA 7A) DI
PELABUHAN KELANG.**

Adalah dimaklumkan bahawa kerja-kerja pengerukan di hadapan dermaga Northport dan Southport/Southpoint akan dijalankan oleh Syarikat Integrated Marine Works Sdn Bhd dan butiran kerja pengerukan adalah seperti berikut ;

Tarikh : 15hb Julai hingga 21hb Oktober 2010

Kawasan Pengerukan :

a) Northport

	Latitud	Longitud
A	03° 03' 02.87" N	101° 21' 20.80" E
B	03° 03' 02.98" N	101° 21' 22.42" E
C	03° 00' 52.99" N	101° 21' 22.45" E
D	03° 00' 52.64" N	101° 21' 24.07" E

b) Southport/Southpoint

	Latitud	Longitud
A	02° 59' 53.01" N	101° 23' 28.67" E
B	02° 59' 53.47" N	101° 23' 29.09" E
C	02° 59' 20.26" N	101° 23' 38.21" E
D	02° 59' 20.32" N	101° 23' 38.99" E

**DREDGING WORKS AT NORTHPORT
WHARVES FRONTAGE (WHARVES 8 TO 25)
AND SOUTH POINT FRONTAGE (WHARVES 1
TO 7A) AT NORTHPORT (MALAYSIA) BHD AT
PORT KELANG.**

This is to notify that the dredging works at Northport wharves frontage and Southport/Southpoint wharves frontage will be carried out by Integrated Marine Works Sdn Bhd and the details of the dredging works are as follows ;

Dates : 15th July 2010 to 21st October 2010

Dredging Area :

c) Northport

	Latitude	Longitude
A	03° 03' 02.87" N	101° 21' 20.80" E
B	03° 03' 02.98" N	101° 21' 22.42" E
C	03° 00' 52.99" N	101° 21' 22.45" E
D	03° 00' 52.64" N	101° 21' 24.07" E

d) Southport/Southpoint

	Latitude	Longitude
A	02° 59' 53.01" N	101° 23' 28.67" E
B	02° 59' 53.47" N	101° 23' 29.09" E
C	02° 59' 20.26" N	101° 23' 38.21" E
D	02° 59' 20.32" N	101° 23' 38.99" E

Kawasan Pelupusan ;

	Latitude	Longitude
A	02° 56' 33" N	101° 07' 16" E
B	02° 54' 00" N	101° 10' 05" E
C	02° 54' 57" N	101° 05' 50" E
D	02° 54' 29" N	101° 07' 58" E

Vesel yang terlibat ;

Nama Vesel	Jenis Vesel
Inai Selasih	Trailing Suction Hopper Dredger

Carta terlibat ;

MAL 5300

Semua vesel-vesel dan pelaut-pelaut adalah dinasihatkan untuk menjauhi dan berhati-hati apabila berhampiran dengan kawasan berkerja.

Sekian, terima kasih.

(HAZMAN BIN HUSSEIN)

Pengarah Laut / Director of Marine

Wilayah Tengah / Central Region

Dumping Ground Area ;

	Latitude	Longitude
A	02° 56' 33" N	101° 07' 16" E
B	02° 54' 00" N	101° 10' 05" E
D	02° 54' 57" N	101° 05' 50" E
E	02° 54' 29" N	101° 07' 58" E

Vessel Involved ;

Name of Vessel	Type of Vessel
Inai Selasih	Trailing Suction Hopper Dredger

Chart effected ;

MAL 5300

All vessel and mariners in the vicinity are advised to navigate with caution and keep clear of the working area.

Thank you.

