



PEKELILING PELABUHAN NO. 05/2004
PORT CIRCULAR NO. 05/2004

DARIPADA : PENGARAH LAUT WILAYAH SELATAN
FROM : DIRECTOR OF MARINE SOUTHERN REGION

KEPADA : SEMUA NAKHODA KAPAL, PELAUT, PEMILIK & AGEN
PERKAPALAN DAN MASYARAKAT PERKAPALAN AMNYA.
TO : ALL SHIP MASTERS, MARINERS, SHIP OWNERS & AGENTS
AND THE GENERAL SHIPPING COMMUNITY.

TARIKH/DATED : 22 MAC 2004 / 22 MARCH 2004

**PENUBUHAN KAWASAN KERJA DI TG.
BIN, KUALA SG. PULAI, JOHOR.**

Ina adalah untuk memaklumkan bahwa satu kawasan kerja telah ditubuhkan bagi memudahkan kerja-kerja pembinaan sebuah stesen janakuasa di Tg. Bin di Kuala Sg. Pulai, daerah Pontian, Johor.

Kawasan kerja tersebut adalah bersempadankan kordinat-kordinat geografika seperti berikut :

	Latitud Utara	Longitud Timur
A	01° 20 .24'	103° 32. 83'
B	01° 20. 29'	103° 32. 90'
C	01° 20. 20'	103° 32. 96'
D	01° 20. 15'	103° 32. 88'

Kerja-kerja akan melibatkan pergerakan vesel-vesel kerja dan pemunggahan bahan-bahan binaan dan peralatan berat ke jeti sementara yang bakal dibina di dalam kawasan kerja tersebut. Waktu bekerja di kawasan kerja ini adalah 24 jam setiap hari dan dijangka akan selesai pada penghujung Disember 2007.

PERHATIAN

Semua vesel adalah dinasihatkan untuk menjauhi dan mengurangkan kelajuan apabila melalui kawasan kerja tersebut.

Carta terlibat : MAL 5123

**ESTABLISHMENT OF A WORKING AREA
AT TG. BIN, KUALA SG. PULAI, JOHOR.**

This is to notify that a working area has been established to facilitate the construction of a power station at Tg. Bin at the mouth of Sg. Pulai, district of Pontian, Johor.

The working area are bounded by the following geographical coordinates:

	North Latitude	East Longitude
A	01° 20 .24'	103° 32. 83'
B	01° 20. 29'	103° 32. 90'
C	01° 20. 20'	103° 32. 96'
D	01° 20. 15'	103° 32. 88'

Works will involve the movement of working vessels and offloading of construction materials and heavy equipment at a temporary jetty, which will be constructed within the working area. Working hours within this working area is 24 hours daily and is expected to be completed end of December 2007.

CAUTION

All vessels are advised to keep clear of and to reduce speed when passing the said working area.

Charts affected : MAL 5123

PEKELILING PELABUHAN NO. 05/2004 muka surat 2/2
PORT CIRCULAR NO. 05/2004 page 2/2

Sekian, terima kasih.

“BERKHIDMAT UNTUK NEGARA”

Saya yang menurut perintah,

(HAZMAN BIN HUSSEIN)
Pengarah Laut/*Director of Marine*
Wilayah Selatan/*Southern Region*