



MALAYSIA MARINE DEPARTMENT
MARINE HEADQUARTERS
P.O BOX 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN
MALAYSIA



PENINSULAR NOTICE TO MARINERS NTM 112(T)/2023

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Dickson Waters

Charts Affected : MAL 5239
BA 3946

**PORT DICKSON FAIRWAY LIGHT BUOY UNLIT
PORT DICKSON WATER**

Mariners are advised that Port Dickson Fairway Light Buoys is unlit. Details are as follows:

Name : Port Dickson Fairway
Position : Lat. 02° 30.000' N
Long. 102° 42.766' E
Light Characteristic : LFI.W.10s

Mariners are advised to navigate with caution when in the vicinity.

(Ts. MUHAMMAD FADHLI BIN MAKHTAR)
for The Director General,
Malaysia Marine Department
31th May 2023

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602