



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 05(T)/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Tumpat Waters, Kelantan
Charts Affected : MAL 664
 BA 3543

TUMPAT WRECK BUOY TEMPORARILY WITHDRAWN TUMPAT WATERS, KELANTAN

Mariners are advised that Tumpat Wreck buoy has been destroyed.

Name : Tumpat Wreck buoy
Position : Latitude 06° 14.300' N
 Longitude 102° 09.190' E
Light Characteristic : FL.G.5s
Type : Starboard Hand

This notice cancels NTM 207T/2021.

Mariners are advised to navigate with caution when in the vicinity.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
13th January 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602