



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



**BORNEO NORTH WEST COAST**

**179/2021(T) – C BUOY, BINTULU PORT – MISSING**

C Buoy at position 03°15'32.204"N 113°00'35.133"E is reported missing. Mariners are advised to navigate with caution when in vicinity.

Charts : SAR 401, SAR 402 & SAR 4001

Source : Sarawak Marine Department

Date : 25<sup>th</sup> November 2021

**" BERKHIDMAT UNTUK NEGARA "**

**[ RADUAN BIN SERAP ]**

For Director of Marine Sarawak

***"Safer Ships, Secure Ports, Cleaner Seas"***



Cert. No: ISO 9001-0047621, ISO 9001-0047600