



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 197(R)/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Malacca Strait
Charts Affected : MAL 532, MAL 540 & MAL54
BA 1143

CORRIGENDUM TO NTM 197/2022 **NEW LIGHT BUOY ESTABLISHED IN POSITION** **MALACCA STRAITS**

Mariners are advised that new light buoy have been established in position in Malacca Strait:

Name : **Batuan Penyu**
Position : **Lat. 03° 13.740' N,**
Long. 101° 12.680' E
Range : **5 Nm**
Light Characteristic : **Q(9).15S**
Type : **West Cardinal Mark**

Mariners are advised to take extra caution when navigating in the vicinity.
This notice cancel NTM 197/2022.

(EMIZUL FADLY BIN MASDEK)
for The Director General,
Marine Department Malaysia.
13th December 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602