



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 55/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Malacca Straits

Charts Affected : MAL 540 & MAL 532
 BA 3940 & BA 3946

ISOLATED DANGER MARK LIGHT BUOY PERMANENTLY WITHDRAWN MALACCA STRAIT

Mariners are advised that an isolated danger mark light buoy have been permanently withdrawn.

Name : OFB Wreck

Type : Isolated Danger Mark

Position : Lat. 02° 56.63' N, Long. 100° 59.49' E (WGS 84)

Light Characteristic : Fl(2)10s

This notice cancels NTM 87/2019.

Mariners are advised to navigate with caution when in the vicinity.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
21th April 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602