



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 74/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6359
 BA 3446 & BA 1379

KUANTAN PORT LEADING LIGHT 311° 04 REAR LIGHT BEACON RESTORED TO NORMAL KUANTAN PORT, PAHANG

Mariners are advised that Kuantan Port Leading Light 311° 04 Rear Light Beacon restored to normal.

Name : Kuantan Port Leading Light 311° 04 Rear

Position : Lat. 03° 58.940' N
 Long. 103° 25.490' E

Light Characteristic : Oc.G.5s

This notice cancels NTM68(T)/2022.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
29th May 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602