



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 30T/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : Mal 664
 BA 771

KUALA BESAR FAIRWAY LIGHT BUOY TEMPORARILY WITHDRAWN KUALA BESAR, KELANTAN

Mariners are advised that Kuala Besar Fairway Light Buoy have been temporarily withdrawn.

Name : Kuala Besar Fairway Light Buoy
Position : Lat. 06° 14.000' N,
 Long. 103° 14.120' E
Light Characteristic : LFI.W.10s

Mariners are advised to navigate with caution when in the vicinity.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
01st March 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602