



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 208/2021

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia
Position : Straits of Malacca
Charts Affected : MAL 5530 & MAL 5536
BA 1366

RIMAU 2R LIGHT BUOY ALTERED IN POSITION STRAITS OF MALACCA

Mariners are advised that Rimau 2R Light Buoy has been altered in position.

Name : Rimau 2R
New Position : Lat. 05° 16.690' N,
Long. 100° 18.080' E
Light Characteristic : FL.R.4s
Type : Porthand

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
23th November 2021

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602