



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

166/2021(T) – BINTULU PORT SOUTH ACCESS CHANNEL - BUOY K

Buoy K *Fl. G. 5s* at position 03°15'08.440"N, 113°02'33.201"E, has been moved to position 03°15'11.392"N, 113°02'31.978"E.

2. Mariners are advised to navigate with caution in the area.

3. Notice No. 25/2021(T) is cancelled.

Charts : SAR 401, SAR 402 & SAR 4001

Source : Sarawak Marine Department

Date : 5th November 2021

" BERKHIDMAT UNTUK NEGARA "

[MUHAMAD SAHABULLAH BIN KASIM]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600