



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

132/2022(T) – BUOY S AT SOUTH ACCESS CHANNEL, BINTULU PORT – RESTORED TO NORMAL

Buoy S at position 03° 14' 55.910"N, 113° 03' 57.326"E, has been restored to normal.
Notice 130/2022(T) is hereby cancelled.

Charts : SAR 401, SAR 402 & SAR 4001
Source : Sarawak Region Marine Department
Date : 17th October 2022

"BERKHIDMAT UNTUK NEGARA"

[RADUAN BIN SERAP]

For Director of Marine Sarawak

“Safer Ships, Secure Ports, Cleaner Seas”



Cert. No: ISO 9001-0047621, ISO 9001-0047600