



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 123/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6416
 BA 1374

TANJUNG BERHALA NO.1 LIGHTBUOY RESTORED TO NORMAL KEMAMAN PORT, TERENGGANU

Mariners are advised that a Tanjung Berhala No.1 Light buoy has been restored to normal at Kemaman Port, Terengganu. The details are as follows:

Name : Tanjung Berhala No.1 Light buoy

Position : Lat. 04° 13.702' N
 Long. 103° 29.314' E

Light Characteristic : Fl.G.5s

Mariners are advised to navigate with caution when in the vicinity.

This notice cancel NTM 114(T)/2022.

(EMIZUL FADLY BIN MASDEK)

for The Director General,
Marine Department Malaysia.
20th August 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602