



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 111(T)/2021**

Telefon           : 03-3346 7777    Emel            : [kpgr@marine.gov.my](mailto:kpgr@marine.gov.my)  
Faksimili       : 03-3168 5289    Laman Web   : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia  
Position           : Malacca Strait  
Charts Affected   : MAL 521 & MAL 54  
                          BA 3947, BA 3946 & BA 1358

---

### **PULAU UN DAN LIGHTHOUSE REDUCED POWER MALACCA STRAIT**

---

Mariners are advised that Pulau Undan Lighthouse is temporarily operating on reduced power and light nominal range is reduced to 15 nautical miles.

Name               : Pulau Undan Lighthouse  
Position           : Lat.    02° 02.900' N  
                          Long. 102° 20.100' E  
Characteristic     : Fl.2.W.15s

Mariners are advised to navigate with caution.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
26<sup>th</sup> June 2021

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602