



NOTICE TO MARINERS NTM 04(T)/2021

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
 Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 515
 BA 2403

**UNDERWATER CABLE SYSTEM REPAIR AND MAINTENANCE OPERATION FOR
 SEAX-1
 JOHOR WATERS**

Mariners are advised that an underwater cable system repair and maintenance operation is being carried out for SEAX-1 in Johor Waters. The details are as follows:

Duration: 3rd – 23rd January 2021 (21 days)

Vessels Involved:

Name : Asean Explorer	Name : Johan Pioneer 2
Type : Cable Laying Vessel	Type : Tug
Flag : Indonesia	Flag : Malaysia
Callsign : JZSY	Callsign : 9WGN5

Area:

Point	Latitude	Longitude
Estimated Faulty Point	01° 40.326' N	104° 35.272' E
1	01° 48.244' N	104° 32.582' E
2	01° 48.244' N	104° 34.200' E

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
 CERT. NO.: QMS 03602

Point	Latitude	Longitude
3	01° 42.298' N	104° 33.467' E
4	01° 38.733' N	104° 38.212' E
5	01° 31.980' N	104° 36.245' E
6	01° 32.401' N	104° 34.628' E
7	01° 38.203' N	104° 36.687' E
8	01° 41.662' N	104° 31.978' E

Above coordinates are referenced to Datum: WGS-84

Mariners are advised to navigate with caution when in the vicinity and keep clear of the working area.

(RINA MASLINA BINTI BAHARUDIN)

for The Director General,
Marine Department Malaysia.
04th January 2021

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602