



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 183(T)/2022**

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web     : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Port Klang waters

Charts Affected   : MAL 5300  
                          BA 3945

---

### **TERUSAN LIGHT BUOY UNLIT PORT KLANG WATERS**

---

Mariners are advised that Terusan Light Buoy unlit.

Name                : Terusan  
Position            : Lat.    02° 51.048' N  
                          Long. 101° 15.035' E  
Light Characteristic : Fl.R.10s

Mariners are advised to navigate with caution in the area.

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
23<sup>th</sup> November 2022

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602