



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



**BORNEO NORTH WEST COAST**

**182/2021(T) – STARBOARD HAND BUOY, KUALA KEMENA - MISSING**

Starboard Hand Buoy at position 03°11'06.307"N 110°37'38.900"E is reported missing. Mariners are advised to navigate with caution when in vicinity.

Charts : SAR 401, SAR 402 & SAR 4001

Source : Sarawak Marine Department

Date : 6<sup>th</sup> December 2021

**" BERKHIDMAT UNTUK NEGARA "**

**[ RADUAN BIN SERAP ]**

For Director of Marine Sarawak

***"Safer Ships, Secure Ports, Cleaner Seas"***



Cert. No: ISO 9001-0047621, ISO 9001-0047600