



**JABATAN LAUT MALAYSIA**  
**IBU PEJABAT LAUT**  
**PETI SURAT 12, JALAN LIMBUNGAN**  
**42007 PELABUHAN KLANG**  
**SELANGOR DARUL EHSAN**



## **NOTICE TO MARINERS      NTM 107/2021**

Telefon           : 03-3346 7777   Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289   Laman Web     : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Malacca Straits

Charts Affected   : MAL 54 & MAL 540  
                          BA 3901 & BA 3945

---

### **ONE FATHOM BANK LIGHTHOUSE RESTORED TO NORMAL MALACCA STRAITS**

Mariners are advised that One Fathom Bank Lighthouse has been restored to normal.

Name                : One Fathom Bank

Position            : Lat.        02° 53.31' N  
                          Long.      100° 59.72' E

Elevation           : 43 m from MHWS

Characteristic     : FI (4) W 20S

This notice cancels NTM 116(T)/2020

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
22<sup>nd</sup> June 2021

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602