



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## NOTICE TO MARINERS      NTM 101/2022

Telefon           : 03-3346 7777    Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289    Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : Port Klang waters

Charts Affected   : MAL 5307  
                          BA 3945

---

### PORT KLANG NO.8 LIGHT BUOY RESTORED TO NORMAL PORT KLANG WATERS

---

Mariners are advised that Port Klang No.8 Light Buoy restored to normal.

Name               : Port Klang No.8

Position           : Lat.   03° 05.210' N  
                          Long. 101° 19.290' E

Light Characteristic : FL(4).R.10s

Mariners are advised to navigate with caution in the area.

This notice cancels NTM 93(T)/2022

**(MOHD IZUAN BIN ISNAN)**  
for The Director General,  
Marine Department Malaysia.  
25<sup>th</sup> July 2022

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602