



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



**BORNEO NORTH WEST COAST**

**84/2022(T) – BUOY SIP 13, SAMALAJU PORT – MISSING**

Buoy SIP 13 at position 03°34'29.100"N 113°18'47.300"E is reported missing.  
Mariners are advised to navigate with caution in the area.

Charts : SAR 501 & SAR 5001  
Source : Sarawak Region Marine Department  
Date : 12<sup>th</sup> July 2022

**"BERKHIDMAT UNTUK NEGARA"**

**[ RADUAN BIN SERAP ]**  
For Director of Marine Sarawak

**"Safer Ships, Secure Ports, Cleaner Seas"**



Cert. No: ISO 9001-0047621, ISO 9001-0047600