



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



**BORNEO NORTH WEST COAST**

**47/2022(T) - MAINTENANCE, PIPELINE REPLACEMENT AND EQUIPMENT REPAIR WORKS AT BOKOR OIL PLATFORM (BODP-A, BOP-A, BOK-A, BODP-B) FOR INTEGRATED BOKOR PHASE 3 EOR & BETTY REDEVELOPMENT PROJECTS, OFFSHORE SARAWAK**

Mariners are advised that PETRONAS Carigali Sdn Bhd will carry out maintenance, pipeline replacement and equipment repair works at Bokor oil platform (BODP-A, BOP-A, BOK-A, BODP-B) on 4<sup>th</sup> April 2022 until 24<sup>th</sup> May 2022.

2. The coordinates of location:

Location	Latitude	Longitude
BOP-A	04° 32' 58.263" N	113° 37' 26.807" E
BOK-A	04° 33' 00.740" N	113° 37' 26.201" E
BODP-A	04° 32' 56.054" N	113° 37' 25.553" E
BODP-B	04° 32' 38.648" N	113° 37' 05.389" E

*Positions in WGS 84 Datum*

3. Vessels involved:

Name	Flag	Length	Breadth
SAPURAKENCANA DUYONG	Malaysia	82.00 m	22.00 m
PSALM 38	Malaysia	41.00 m	7.60 m
TAMBAH MAJU	Malaysia	47.00 m	11.00 m

4. Mariners are advised to navigate with caution when in vicinity.

Charts : SAR 1, SAR 2, SAR 4 & SAR 7

Source : PETRONAS Carigali Sdn. Bhd.

Date : 5<sup>th</sup> April 2022

**" BERKHIDMAT UNTUK NEGARA "**

**[ ABANG MOHAMAD BIN ABANG NAILI ]**

For Director of Marine Sarawak

**"Safer Ships, Secure Ports, Cleaner Seas"**



Cert. No: ISO 9001-0047621, ISO 9001-0047600