



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

82/2021(T) - PIPELINE MAINTENANCE AND REPLACEMENT AND EQUIPMENT REPAIR WORKS AT BOKOR FIELD (BODP-A, BOP-A, BOK-A, BODP-B) FOR INTEGRATED BOKOR PHASE 3 EOR & BETTY REDEVELOPMENT PROJECTS, OFFSHORE SARAWAK

Mariners are advised that PETRONAS Carigali Sdn. Bhd. will carry out pipeline maintenance and replacement and equipment repair works at at BODP-A, BOP-A, BOK-A and BODP-B platform at Bokor field, offshore Sarawak on or about 18th June 2021 until 31st August 2021 for a duration of approximately 74 days.

2. Location coordinates:

Location	Latitude	Longitude
BOKOR Field	04° 33' 00.740" N	113° 37' 26.201" E
BODP-A	04° 32' 56.054" N	113° 37' 25.553" E
BOP-A	04° 32' 58.263" N	113° 37' 26.807" E
BOK-A	04° 33' 00.740" N	113° 37' 26.201" E
BODP-B	04° 32' 38.648" N	113° 37' 05.389" E

Positions in WGS 84 Datum

3. Vessels involved:

Name	Flag	Length	Breadth
KEYFIELD FALCON	Malaysia	80.00 m	20.00 m
SMS VENTURE	Malaysia	36.63 m	7.80 m
MK1	Malaysia	46.00 m	10.90 m
BIMA LAPAN	Malaysia	36 m	8 m

4. Mariners are advised to navigate with caution when in vicinity.

Charts : SAR 1, SAR 2, SAR 4 & SAR 7

Source : PETRONAS Carigali Sdn. Bhd.

Date : 17th June 2021

" BERKHIDMAT UNTUK NEGARA "

[RADUAN BIN SERAP]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600