



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 153/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 6441
 BA 3482

KERTIH N3 LIGHT BUOY RESTORED TO NORMAL TERENGGANU WATERS

Mariners are advised that Kertih N3 Light Buoy has been restored to normal.

Name : Kertih N3 Light Buoy

Position : Lat. 04° 34.564' N
 Long. 103° 28.364' E

Light Characteristic : Fl.Y.4s

Mariners are advised to navigate with caution when in the vicinity.

This notice cancels NTM 119(T)/2022.

(EMIZUL FADLY BIN MASDEK)

for The Director General,
Marine Department Malaysia.

10th October 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602