



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS

NTM 198T/2021

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Kelang , Selangor

Charts Affected : MAL 532
BA 8232

TEMPORARY PLACEMENT OF INNOVATION BUOY SELANGOR

Mariners are advised that a temporary Special Mark Buoy has been virtually established in position. The details are as follows:

Name : SIR 2
Position : Lat. 03° 01.170' N
Long. 101° 20.640' E
Light Character : Fl.Y.5s
Description : Special Mark (Yellow)

Mariners are advised to navigate with caution.

(MOHD FAIZAL BIN MOHD NASIR)

for The Director General,
Marine Department Malaysia.

26th October 2021

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602