



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: www.marine.gov.my



**BORNEO NORTH WEST COAST**

**135/2021(T) – BUOY NO. 5, BINTULU PORT – OFF STATION**

Mariners are advised that Buoy No. 5, Bintulu Port Fl. G. 5s 03°15'49.244"N  
113°01'12.592"E is off station and drift to 3°15'46.260"N 113°01'07.200"E.

2. Mariners are advised to navigate with caution in the area

Charts : SAR 401, SAR 402 & SAR 4001

Source : Sarawak Marine Department

Date : 8<sup>th</sup> September 2021

**" BERKHIDMAT UNTUK NEGARA "**

**[ RADUAN BIN SERAP ]**  
For Director of Marine Sarawak

**“Safer Ships, Secure Ports, Cleaner Seas”**



Cert. No: ISO 9001-0047621, ISO 9001-0047600