



**HYDROGRAPHIC OFFICE
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422
Website: www.marine.gov.my



BORNEO NORTH WEST COAST

68/2022(T) – PROPOSED CONSTRUCTION AND COMPLETION OF COASTAL ROAD NETWORK PACKAGE D3A: PROPOSED SECOND KUCHING - SAMARAHAN TRUNK ROAD (BRIDGE OVER SUNGAI SARAWAK AT SEJINGKAT)

Mariners are advised that temporary marker buoys have been installed for navigation aids during construction and completion of bridge across the Sarawak River at Sejingkat.

2. The coordinates of location:

Buoy		Latitude	Longitude
Red Marker Buoy	R1	1° 34' 55.3" N	110° 25' 20.9" E
	R2	1° 34' 42.1" N	110° 25' 14.7" E
	R3	1° 34' 36" N	110° 25' 07.4" E
Green Marker Buoy	G1	1° 34' 55.3" N	110° 25' 20.9" E
	G2	1° 34' 50.0" N	110° 25' 12.2" E
	G3	1° 34' 43.6" N	110° 25' 3.6" E
	G4	1° 34' 40.1" N	110° 25' 11.95" E
Yellow Marker Buoy	Y1	1° 34' 52.9" N	110° 25' 15.8" E
	Y2	1° 34' 45.0" N	110° 25' 18.7" E
	Y3	1° 34' 47.9" N	110° 25' 8.8" E

Positions in WGS 84 Datum

3. Mariners are advised to navigate with caution when in vicinity and NTM No. 19/2022(T) dated 8th February 2022 refers.

Charts : SAR 102 & SAR 104
Source : Sarawak Rivers Board
Date : 20th May 2022

" BERKHIDMAT UNTUK NEGARA "

[RADUAN BIN SERAP]

For Director of Marine Sarawak

"Safer Ships, Secure Ports, Cleaner Seas"



Cert. No: ISO 9001-0047621, ISO 9001-0047600