



**JABATAN LAUT MALAYSIA**  
IBU PEJABAT LAUT  
PETI SURAT 12, JALAN LIMBUNGAN  
42007 PELABUHAN KLANG  
SELANGOR DARUL EHSAN



## NOTICE TO MARINERS      NTM 199(T)/2022

Telefon           : 03-3346 7777   Emel               : [kpqr@marine.gov.my](mailto:kpqr@marine.gov.my)  
Faksimili        : 03-3168 5289   Laman Web      : <http://www.marine.gov.my>

---

Authority           : Director of Marine, Malaysia

Position           : South China Sea

Charts Affected   : MAL 6257  
                          BA 3445

---

### MARINA TIOMAN BREAKWATER PORT LIGHT BEACON UNLIT SOUTH CHINA SEA

---

Mariners are advised that Marina Tioman Breakwater Port Light Beacon unlit.

Name               : Marina Tioman Breakwater Port

Position           : Lat.    02° 49.163' N  
                          Long. 104° 09.388' E

Light Characteristic : Q.R

Mariners are advised to navigate with caution in the area.

**(Ts. MUHAMMAD FADHLI MAKHTAR)**  
for The Director General,  
Marine Department Malaysia.  
7<sup>th</sup> Disember 2022

---

*Safer Ships, Secure Ports, Cleaner Seas*



CERTIFIED TO ISO 9001:2015  
CERT. NO.: QMS 03602