



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 133(T)/2022

Telefon : 03-3346 7777 Emel : kpgr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Malacca Strait

Charts Affected : MAL 554
 BA 3944

PULAU RIMAU LIGHTHOUSE UNLIT MALACCA STRAIT

Mariners are advised that Pulau Rimau Lighthouse unlit in position.

Name : Pulau Rimau Lighthouse

Position : Lat. 05° 14.680' N
 Long. 100° 16.500' E

Light Characteristic : Fl.2.W.10s

Mariners are advised to navigate with caution when in the vicinity.

(Ts. MUHAMMAD FADHLI MAKHTAR)

for The Director General,
Marine Department Malaysia.

12th September 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602