



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 05/2021

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : South China Sea

Charts Affected : MAL 635
 BA 1379 & BA 3446

**KUANTAN PORT LEADING LIGHT 311° 04 REAR LIGHT BEACON RESTORED TO
NORMAL
KUANTAN PORT, PAHANG**

Mariners are advised that Kuantan Port Leading Light 311° 04 Rear Light Beacon has been restored to normal. The details are as follows:

Name : Kuantan Port Leading Light 311° 04 Rear

Position : Lat. 03° 58.960' N
 Long. 103° 25.590' E

Light Characteristic : OC.G.5s

This notice cancels NTM 290(T)/2020.

(MOHD IZUAN BIN ISNAN)
for The Director General,
Marine Department Malaysia.
6th January 2020