



JABATAN LAUT MALAYSIA
IBU PEJABAT LAUT
PETI SURAT 12, JALAN LIMBUNGAN
42007 PELABUHAN KLANG
SELANGOR DARUL EHSAN



NOTICE TO MARINERS NTM 73/2022

Telefon : 03-3346 7777 Emel : kpqr@marine.gov.my
Faksimili : 03-3168 5289 Laman Web : <http://www.marine.gov.my>

Authority : Director of Marine, Malaysia

Position : Port Klang waters

Charts Affected : MAL 540
 BA 3945

PORT KLANG NO.13 LIGHT BUOY UNLIT PORT KLANG WATERS

Mariners are advised that Port Klang No.13 Light Buoy has been restored to normal.

Name : Port Klang No.13

Position : Lat. 03° 03.017' N
 Long. 101° 20.767' E

Light Characteristic : Fl(2).G.5s

This notice cancels NTM62(T)/2022.

(EMIZUL FADLY BIN MASDEK)
for The Director General,
Marine Department Malaysia.
27th May 2022

Safer Ships, Secure Ports, Cleaner Seas



CERTIFIED TO ISO 9001:2015
CERT. NO.: QMS 03602