



**HYDROGRAPHIC OFFICE  
JABATAN LAUT MALAYSIA WILAYAH SARAWAK**

**NOTICE TO MARINERS  
(NOTIS PELAUT)**

TEL: 082-484159 TELEX: LAUT MA 70933 FAX: 082-331778, 082-339422  
Website: [www.marine.gov.my](http://www.marine.gov.my)



**BORNEO NORTH WEST COAST**

**159/2022(T) – RACON BUOY – SIPS1, SAMALAJU PORT - MISSING**

Racon Buoy - SIPS1 at position 03°38'02.114"N 113°15'22.126"E is reported missing.  
Mariners are advised to navigate with caution in the area.

Charts : SAR 501 & SAR 5001  
Source : Sarawak Region Marine Department  
Date : 28<sup>th</sup> December 2022

**"BERKHIDMAT UNTUK NEGARA"**

**[ MUHAMAD SAHABULLAH BIN KASIM ]**

For Director of Marine Sarawak

***Safer Ships, Secure Ports, Cleaner Seas***



Cert No: ISO 9001-0047600, ISO 9001-0047621